# DIGITAL CAP THE MAXX® PRESS

# **OPERATOR'S MANUAL**





# When using your heat press, basic precautions should always be followed, including the following:

- 1. Read all instructions.
- 2. Use heat press only for its intended use.
- 3. To reduce the risk of electric shock, do not immerse the heat press in water or other liquids.
- 4. Never pull cord to disconnect from outlet, instead grasp plug and pull to disconnect.
- 5. Do not allow cord to touch hot surfaces and allow heat press to cool completely before storing.
- 6. Do not operate heat press with a damaged cord or if the equipment has been dropped or damaged. To reduce the risk of electric shock, do not disassemble or attempt to repair the heat press. Take it to a qualified service person for examination and repair. Incorrect assembly or repair could increase the risk of fire, electric shock, or injury to persons when the equipment is used. Power supply cord must be disconnected before cleaning or servicing press.
- 7. This appliance is not intended for use by persons (including children) with reduced physical, sensory or mental capabilities, or lack of experience and knowledge, unless they have been given supervision or instruction concerning use of the appliance by a person responsible for their safety.
- 8. Close supervision is necessary for any heat press being used by or near children. Do not leave equipment unattended while connected.
- 9. To avoid burns, do not touch hot metal parts or the heated platen during use.
- 10. To reduce the likelihood of circuit overload, do not operate other high voltage equipment on the same circuit.
- 11. If an extension cord is necessary, then a 20-amperage rated cord should be used. Cords rated for less amperage may overheat. Care should be taken to arrange the cord so that it cannot be pulled or tripped over.
- 12. Keep hands clear of the upper heat press platen during lock down as the pressure may cause injury.
- 13. Heat press should be placed on a sturdy, suitable stand at least 36"L x 24"W x 29"H.
- 14. Work area must be kept clean, tidy and free of obstructions.

#### **Product Warranty Registration**

#### Log onto www.Hotronix.com/registration

You must provide the Hotronix<sup>®</sup> heat press serial number and model information.

#### **Table Of Contents**



- Safety Instructions 2
  - Machine View 4
- Control Panel Guide 5

#### **Operating Instructions** 6-8

- Connecting the System 6
  - Start Up/Shut Down 6
- Adjusting Temperature 7
  - Adjusting Time 7
  - Adjusting Pressure 8
  - Printing/Pressing 8
- Electrical Schematic 9
- Parts Location Guide 10
- Replacement Parts List 11
  - Contact 12



### **Machine View**

Circuit

Breaker



SERVICE HOTLINE: 800.727.8520

4

### **Control Panel Guide**



WWW.HOTRONIX.COM 5

### **Operating Instructions**

#### **Connecting the System**

### Start Up/Shut Down



Connect the power cord into a properly grounded electrical outlet with a sufficient amperage rating.

#### Voltage

**120 volt** requires a full 20-amp grounded circuit. **220 volt** requires a full 10-amp grounded circuit.

**Extension Cords** should be as short as possible and not less than 12 gauge. Heavy duty cords are recommended.

**Circuits** with less than 10 amps or have other high demand equipment or heat presses plugged in should not be used.

**Note:** If the supply cord is damaged, it must be replaced by the manufacturer, its service agent or a similarly qualified person in order to avoid hazard. Use SJT type rated 300 V cord for replacement.

#### CAUTION

#### Failure to follow these instructions will cause:

- 1. Erratic controller functions.
- 2. Inaccurate displays and slow heat up.
- 3. The circuit breaker to disengage.



Locate the lift handle and position the heat platen in the UP position.



Locate the Power ON/OFF Switch on the side of the press, then turn the Power Switch ON.

#### **Adjusting Temperature**



Press the Mode Select button in the center of the Control Panel.

The (SET) and (TEMP) lights located next to the display will illuminate.

Press the (+) or (-) button to raise or lower the temperature setting.

The temperature can be set from 205°F (96°C) to 430°F (220°C). The LED Display will show changes as you make them.

**Note:** The temperature indicator will only display temperatures 200°F (93°C) and up.

#### **Adjusting Time**



Once you have adjusted the temperature, press the Mode Select button again to advance to Time Mode.

The (SET) and (TIME) lights will illuminate.

Adjust the time in the same manner you adjusted the temperature.

Select the desired time and push the Mode Select button again to exit.

All lights will be off and the press will return to PRINT mode.

### **Operating Instructions**

### **Adjusting Pressure**




The Pressure Adjustment Knob is located directly under the lower platen.

Turn the knob clockwise to increase pressure and counterclockwise to decrease pressure.

**Remember** to allow for the thickness of your cap when adjusting the pressure.

**WARNING:** Structural damage caused by excessive pressure is not covered under the limited warranty!

### **Printing/Pressing**




Once your equipment has reached the designated temperature:


- Pull the Cap Hold Down Lever up and towards the operator and load the cap onto the lower platen.
- Pull out the sweatband and position the cap so it clears the upper platen when the machine is closed.
- Push the Cap Hold Down Lever down and away from the operator to stretch the cap and keep it from shifting.
- Position your design and lower and lock the heat platen into the PRESS position to begin the automatic timing process.
- The timer will automatically count down and audibly signal you to lift the heat platen into the UP position when the print cycle is complete.

### **Electrical Schematic**

#### US 120V/240V VERSION



#### CE 230V VERSION



### **Parts Location Guide**



10

## **Replacement Parts List**

ITEM #	PART #	DESCRIPTION	QTY	ITEM #	PART #	DESCRIPTION	QTY
1	4-1172-B	Control Housing, MAXX	1	40	1-1023	Adjustment Spindle, STX 6x6	1
3	1-2018	Controller Overlay, MAXX	1	41	1-1095	Knob, Black Plastic 3/8"-16	1
4	1-2105	Grommet, 9/32" ID 3/8" OD	2	42	1-1051	Bronze Washer	1
5	3-1011-235	Screw, Sheet Metal #6 x 1/2"	6	44	2-1050-C	Cap Platen, Standard 3.5" x 6"	1
6	2-1006-50	Nut, #6-32 Hex with Lockwasher	9	45	1-1050	Silicone Pad, Cap 3.5" x 6" Gray	1
7	3-1011-130	Screw, Pan Phillips #4-40 x 1"	2	46	2-1042	Cap Hold Down	1
8	1-1759	Power Inlet	1	47	1-1089	Cap Hold Down Vinyl Cover	1
9	1-2087	Power Switch	1	48	1-1073	Spring	1
10	3-1011-19	Screw, Machine #6-32 x 1/2"	7	51	1-2246	Gas Spring 11x15 & 6x6 & Cap	1
11	3-1011-25	Screw, Machine #6-32 x 1/4"	5	52	KIT 3-6907-1	Base, MAXX Cap	1
12	1-1353	Conduit Fitting, 1/2" Topaz Straight Twist-On	2	59	3-1011-252	Screw, Pan Phillips #6-32 x 3/4"	1
13	Kit 3-6946	Controller Kit, MAXX	1	60	1-1939	Ball Stud 10mm	2
14	2-1006-51	Nut, #4-40 with Tooth Washer	8	61	2-1006-20	Nut, Hex Nylok 5/16"-18	3
15	2-1661	Controller Bracket, STX MAXX	1	62	3-1011-182	Acorn Nut 10-32	5
16	1-1059	TRIAC	1	63	1-1256	Rubber Foot	6
17	3-1011-22	Screw, Machine #4-40 x 3/8"	6	64	3-1011-164	Screw, Button Socket Head #10-32 x 1/2"	5
18	1-1290	Terminal Block, 5 Contact High Voltage	1	65	1-1085	Eyebolt	1
20	1-1211	Proximity Switch	1	66	2-1006-56	Nut, Nylok #8-32	1
21	1-2317	Circuit Breaker 5A (CAP 6x6)	1	67	KIT 3-6908-1	Heater Arm Assembly, MAXX Cap	1
24	KIT 3-6910-1	Handle Assembly, MAXX Cap	1	70	1-1049-5	PVC Spacer, 1/2" x 3.80"	1
26	1-2440	Shaft Collar, STX6LR Medium	2	71	2-1055-29	Steel Pin, 1/2" x 4.69"	1
27	1-2085-4	Magnet Bracket, MAXX Cap	1	72	1-1049-3	PVC Spacer, 1/2" x 5/8"	2
28	1-1219	Proximity Magnet	1	73	3-1011-55	Screw, Shoulder 3/8" x 1-1/4" w/ 5/16"-18 Thread	1
29	2-1055-26	Steel Pin, 1/2" x 6.45"	2	74	1-2253	Heat Platen, Cap 120V/220V	1
30	1-1048-3	Washer, 1/2" Nylon	4	76	1-1017-2	Pin, Clevis 3/8" x 1-5/8"	2
31	1-1107-1	Hub Cap 1/2"	8	77	1-1043-2	Retaining Clip, Rue Ring	2
32	2-1055-9	Steel Pin, 1/2" x 5-7/8"	1	79	3-1011-87	Screw, SS Phillips #8-32 X 1/4"	5
33	1-1049-1	PVC Spacer, 1/2" x 3.30"	2	80	1-1272-1	Temperature Probe	1
34	1-1049-14	PVC Spacer, 1/2" x 0.70"	2	81	1-2076	Thermostat Disc	1
35	2-1006-2	JCN - NUT	2	82	3-1011-98	Screw, SS Sheet Metal #4 X 1/4"	2
36	1-1042-1	All Thread Pin	1	83	2-1663	Heat Platen Cover, Cap	1
37	1-1049-11	PVC Spacer, 1/2" x 5"	1	84	1-1048-2	Conduit, STX MAXX Cap, 13"	1
38	1-1540	Foam Grip, Black	1	85	1-1063	Washer, Plastic Finishing	2
39	KIT 3-6957	Lift Link, MAXX 6x6 & Cap	2	86	3-1011-217	Screw, Flat Head Phillips #10-24 x 7/16"	2

# **CONTACT US**

#### STAHLS' Hotronix®

One Industrial Park Carmichaels, PA 15320 U.S.A.

#### **Technical Support**

hotronix.com/support

#### **Customer Service**

customerservice@hotronix.com

#### **Replacement Parts**

hotronix.com/locationspart

Web hotronix.com



This document includes multiple trademarks and describes equipment covered by many patents that are owned by GroupeSTAHL and/or its subsidiaries. GroupeSTAHL enforces its rights to protect these intellectual properties. ©2022