


CAD-CUT® GLAZE



FEED MATERIAL into cutter so that the carrier is on the bottom



PREHEAT & POSITION
 Preheat garment for 10 seconds, prior to application. Position weeded design on garment with the carrier side up (*reads left to right*). **Place cover sheet over graphic.**

Recommended Fabrics:

Synthetic Fibers:

Polyester
 Uncoated Nylons

Natural Fibers:

Cotton
 Poly/Cotton Blends

Accessories Required:

Kraft Paper or Reusable Cover Sheet



CUT LOGO, words or numbers in reverse (*mirror image*).



HEAT APPLY
Synthetic Fibers
 Temperature: 265°F-285°F
Natural Fibers/Blends
 Temperature: 285°F-300°F

Time: 8-10 seconds
 Pressure: Medium
 55-60 PSI

Care Instructions

Turn garments inside out. Machine wash on normal cycle. Wash warm, tumble dry low. Do not bleach. Do not dry clean. Do not iron over screen printed transfers.

Not recommended for multi-layered applications.



WEED away excess material leaving only the desired graphic on the carrier for heat transferring.



PEEL COMPLETELY COLD

CUTTER GUIDELINES

CUTTER	BLADE	FORCE	OFFSET	SPEED
Roland GS-24	45° Premium Blade	50-85 gf	.250mm	45 cm/s

All technical information and recommendations are based on tests we believe to be reliable. However, we cannot guarantee performance for conditions not under manufacturer's control. Before using, please determine the suitability of product for its intended use. The user assumes all risk and liability whatsoever in connection with the use of this product. Seller's and manufacturer's only obligation shall be to replace such quantity of the product proved to be defective by manufacturer.

CAD-CUT®, Glaze, & Hotronix® are trademarks & ® trademarks of Stahls' with one or more patents or patents pending.
 © Stahls' 2016 - All International Rights Reserved