

To Order: StahlsID.com • 800.4.STAHLS • Fax: 800.346.2216 International: StahlsInternational.com • 586.772.5551 Canada: StahlsCanada.com • 800.521.5255

.UE PRINT™



MATERIAL into plotter/ cutter so that the media faces up.



PLACE MASK over the graphic, making sure to smooth out any air bubbles.

REMOVE BACKING—



DESIGN in positive form (do not mirror).



PREHEAT & POSITION— Preheat garment for 10 seconds, prior to application. Position & place cover sheet over graphic.

Do not preheat Sublimated Polyester



CUT DESIGN-Most designs may be cut immediately. Some designs may require a 2-4 hour drytime.



HEAT APPLY-

Temperature: 310°F; 154°C Time: 15 seconds Pressure: medium #5 on Hotronix®

Tip: A Heat Printing Pillow or Print Perfect Pad is recommended for even pressure when working around zippers, buttons, heavy seams or mesh reversible jerseys.



WEED Away the excess media.



PEEL MASK WARM—

CUTTER GUIDELINES

| CUTTER | BLADE | FORCE | OFFSET | SPEED |
|---------------------|----------|---------|--------|-----------|
| Roland VP-300 | 45° | 60-80g | .25 | 10-20cm/s |
| Mimaki CG-FX-Series | SPB-0030 | 90-120g | .25 | 10-20cm/s |

Description

White, semi-matte, printable PVC film, for use with solvent, eco-solvent print & cut systems - ensuring perfect opacity and vibrant color reproduction.

Best For

Fabric Banners Table Skirts

Tents

Point of Purchase/Event Displays

Recommended Fabrics

Cotton

Polyester

Poly/cotton blends

Sublimated Polyester — Do not preheat

Due to the combination of fabrics, weaves, coatings and dyes used in the textile industry, Stahls' recommends and provides samples of our materials and medias for testing.

Accessories Required

Medium Tack Magic Mask® Kraft Paper or Reusable Cover Sheet EZ Weeder® or Tweezers

Cutting Notes

Be sure to perform test cuts to ensure proper blade depth when cutting. Cutting too deep will result in weeding or masking difficulties.

Care Instructions

For best results, turn garment inside out before washing. Machine wash warm or hot using mild detergent. Do not bleach. Dry at normal dryer settings on household machines. Do not dry-clean. Do not iron directly on CAD-COLOR® Value Print.

Storage

Do not expose to temperature exceeding 104°F/40°C for a prolonged time. Keep in the original container in a cool & well-ventilated place.

All technical information and recommendations are based on tests we believe to be reliable. However, we cannot guarantee performance for conditions not under manufacturer's control. Before using, please determine the suitability of product for its intended use. The user assumes all risk and liability whatsoever in connection with the use of this product. Seller's and manufacturer's only obligation shall be to replace such quantity of the product proved to be defective by manufacturer.

> CAD-CUT, CAD-COLOR, Solutions & Hotronix are trademarks & ® trademarks of Stahls' ID Direct™ with one or more patents or patents pending. © Stahls' ID Direct™ 2012 - All International Rights Reserved